

DIGITAL THERMO-HYGROMETER

SPECIFICATION

- Measuring Temperature Range: -50°C ~ 70°C (-58°F ~ +158°F)
- Temperature Accuracy: ±1°C (±2°F)
- Selectable °C or °F Display
- Temperature Display Resolution: 0.1°C (0.2°F)
- Measuring Humidity Range: 10%Rh ~ 99%Rh
- Humidity Accuracy: ±5%
- Humidity Display Resolution: 1%
- Max/Min Temperature and Humidity Records
- Operating Voltage: 1.5V, one battery size AAA
- Indoor Relative Humidity & Comfort Level Indicator


Buttons & Operations

1. MIN/MAX Button

- Press MIN/MAX key will display the minimum indoor temperature and minimum indoor humidity.
- Press MIN/MAX key again will display the maximum indoor temperature and maximum indoor humidity.

2. CLEAR Button

- Press CLEAR key will clear the indoor temperature & humidity memory.
- Comfort indicators will display the level as comfortable, wet or dry. The table is shown below.



3 °C and °F Button

- Selectable °C or °F Display by °C and °F Button (or switch).